

| メーカー | メーカー型番 | OS | 動作確認結果 |
|---------|--------------------------|--------------------------------------|--------|
| NEC | LaVie L LL750/GD | Windows XP Home Edition SP2 | ○ |
| | LaVie L PC-LL900FD1Y | Windows XP Home Edition SP3 | ○ |
| | LaVie PC-LL750HG | Windows Vista Home Premium | ○ |
| | LaVie C LC800/MG | Windows Vista Home Premium SP1 | ○ |
| | LaVie C LC900/LG | Windows Vista Home Premium SP1 | ○ |
| | LaVie L LL370/MG | Windows Vista Home Premium SP1 | ○ |
| | LaVie L LL550/MG | Windows Vista Home Premium SP1 | ○ |
| | LaVie L LL850/HJ | Windows Vista Home Premium | ○ |
| | LaVie N LN500/TG6W | Windows Vista Home Premium SP1 | ○ |
| | Lavie L LL550/TG | Windows Vista Home Premium SP1 | ○ |
| Lenovo | 3000 V100 (0763-J3J) | Windows XP Professional SP2 | ○ |
| | ThinkPad R60 (9456-ERJ) | Windows XP Professional SP2 | ○ |
| | ThinkPad T43 (1871-32J) | Windows XP Professional SP2 | ○ |
| | ThinkPad T60 (2007-4AJ) | Windows XP Professional SP2 | ○ |
| | ThinkPad T60 (2623-PKJ) | Windows Vista Business | ○ |
| | ThinkPad T61 (7658-NJJ) | Windows Vista Business | ○ |
| | ThinkPad X200 | Windows XP Professional SP2 | ○ |
| | Ideapad S10e (40682KJ) | Windows XP Home Edition SP3 | ○ |
| FUJITSU | FMV-S8235 (FMVNS4UW3) | Windows XP Professional SP2 | ○ |
| | FMV-C6230 (FMVXN0D52) | Windows XP Professional SP2 | ○ |
| | FMV-BIBLO NB40MN | Windows XP Home Edition SP2 | ○ |
| | FMV-E8240 (FMVNE5FD4) | Windows Vista Business | ○ |
| | FMV-E8250 (FMVNE6CE4) | Windows Vista Business | ○ |
| | FMV-BIBLO NF/A50 | Windows Vista Business | ○ |
| | FMV-BIBLO NF40Y | Windows Vista Home Premium | ○ |
| | FMV-BIBLO NF/D70 | Windows Vista Home Premium SP1 | ○ |
| | FMV-BIBLO S/50D | Windows Vista Home Premium SP1 | ○ |
| SONY | VAIO type S VGN-SZ80S | Windows XP Home Edition SP3 | ○ |
| | VAIO type BX VGN-BX4KANB | Windows Vista Business | ○ |
| | VAIO type F VGN-FE32B/W | Windows Vista Home Premium SP1 | ○ |
| | VAIO type A VGN-AR73DB | Windows Vista Home Premium | ○ |
| | VAIO type N VGN-NR50B | Windows Vista Home Premium | ○ |
| | VAIO type Z VGN-Z70B | Windows Vista Home Premium SP1 | ○ |
| | VAIO type T VGN-TT50B | Windows Vista Home Premium SP1 | ○ |
| | VAIO type C VGN-CS62JB/R | Windows Vista Home Premium SP1 64bit | ○ |
| | VAIO type S VGN-SZ94US | Windows Vista Ultimate | ○ |

■W07K 接続確認済み PC 一覧表

| メーカー | メーカー型番 | OS | 動作確認結果 |
|---------|-----------------------------|--------------------------------|--------|
| TOSHIBA | Dynabook PATX850LS | Windows XP Home Edition SP2 | ○ |
| | Qosmio F40/85F (PQF4085FLR) | Windows Vista Home Premium SP1 | ○ |
| | Qosmio G40/97D (PQG4097DRP) | Windows Vista Home Premium | ○ |
| | Qosmio G40/97E (PQG4097ERP) | Windows Vista Home Premium | ○ |
| DELL | Inspiron 6400 | Windows XP Home Edition SP2 | ○ |
| | Vostro 1400 | Windows XP Professional SP2 | ○ |
| | Latitude D830 | Windows Vista Business | ○ |
| | XPS M1330 | Windows Vista Ultimate | ○ |
| HP | nx6320/CT | Windows XP Professional SP2 | ○ |
| | 2210b/CT | Windows XP Professional SP2 | ○ |
| | Pavilion tx1000 | Windows Vista Home Premium | ○ |
| | 2133 Mini-Note | Windows Vista Home Premium SP1 | ○ |
| GATEWAY | MT3305j | Windows Vista Home Premium | ○ |
| Acer | Aspire5520 AS5520-401G12P | Windows Vista Home Premium | ○ |
| 工人舎 | SC3WP06A/ SC3KP06A | Windows Vista Home Premium SP1 | ○ |
| | SC3KX06A | Windows XP Home Edition SP3 | ○ |
| | SX3KX06MA | Windows XP Home Edition SP3 | ○ |
| ASUS | N10J | Windows Vista Home Premium SP1 | ○ |
| APPLE | MacBookPro (MA601J/A) | 10.4.5 | ○ |
| | MacBookPro (MA896J/A) | 10.4.9 | ○ |
| | MacBookPro (MB133J/A) | 10.5.2 | ○ |
| | MacBookPro (MB134J/A) | 10.5.2 | ○ |
| | MacBookPro (MB604J/A) | 10.5.6 | ○ |

・動作確認はPCメーカー出荷時の状態で行っております。周辺機器を増設、PCの設定変更を行っている場合には別途設定が必要か、正しく動作しない場合があります。

・動作確認済みのPCについては、テストを行った結果、正常動作を確認しておりますが、お客様の環境において、正しく動作を保証するものではありません。